

Aftermarket News (Mar'18)

1. Phased Out Part No.

Fuel Pump

<Background>

Due to Part Number consolidation, 2 Part No. of Fuel Pump has been phased out.

<Next Action>

Please stop order of PN 195131-9320 and place order for PN 195131-9050 instead.

Please stop order of PN 195131-9650 and place order for PN 195130-6990 instead.

For more information, please contact your DENSO Sales Company.