

Aftermarket News (Dec'20)

1. New Product



Introducing new product from DENSO – DIESEL COMMON RAIL INJECTOR.

✓ OE Supplier's precision product

Actual launch timing may differ by country. Please approach your DENSO representative for more details.

Please see below available Part No. and related Carmaker Part No. (vehicle applications information will be provided in e-catalogue in Jan'21):

DENSO P/N	Buond	Carmaker PN	Carmaker PN	
(without Gasket)	Brand	(without Gasket)	(with Gasket)	
SM260100-4010	MITSUBISHI	1465A041		
SM260100-4030	MITSUBISHI	1465A257		
SM260100-6030	MITSUBISHI	1465A439		
SM260100-4000	ΤΟΥΟΤΑ	23670-30240	23670-39236	
SM260100-4020	ΤΟΥΟΤΑ	23670-0L070	23670-09360	
SM260100-4040	ΤΟΥΟΤΑ	23670-0L050	23670-09330	
SM260100-6000	ΤΟΥΟΤΑ	23670-30400	23670-39365	
SM260100-6010	ΤΟΥΟΤΑ	23670-0L090	23670-09350	
SM260100-6020	ΤΟΥΟΤΑ	23670-0L110	23670-09380	
SM260100-6040	ΤΟΥΟΤΑ	23670-0L100	23670-09340	



2. Error in Country of Origin – Ignition Coil

Background

Ignition Coil PN 099700-2121 and PN 099700-2131 were wrongly indicated as "Made in Japan" on packaging box. The correct country of origin is "Made in USA".

Next Action

The rectified version will be progressively available from Feb'21.

3. Wrong Launch - CG Condenser

Background

Last month we shared that CG Condenser PN DI447770-6520 can be used for Volkswagen Polo (2010-2018) with carmaker PN 6R0820411.

This is not correct.

Car Maker	Model	Year	Carmaker PN	DENSO PN	CG PN
VOLKSWAGEN	POLO	2010-2018	6R0820411		DI447770-6520

Next Action

Please do not order CG Condenser PN DI447770-6520 for carmaker PN 6R0820411. Our engineers will develop / further check the application for 6R0820411.

For the previous application of CG PN DI447770-6520 for carmaker PN 6Q0820411, this still remains correct.

For more information, please contact your DENSO Sales Company.