

Aftermarket News (May'21)

1. Product & Box Design Change

New DDS Wiper Blade

<Background>

DNJP and DENSO Wiper Systems, Inc. (DNWS) developed a new STD Design wiper (DDS) as part of cost-down activity.

Changes from current DDS wiper include new product and packaging box design (more details below).

New DDS Wiper PNs will replace all current DDS PNs on running change, subject to each country's stock condition.

*Note: Production: DNWS (Japan), no change from current

<Summary of Main Changes>

_		N 550		
	Current DDS	New DDS	Remarks	
Product	Symmetrical design	Aerodynamic design	Like DDP	
design				
Product	28	8	Reduction of components,	
Components			8 point support -> 2 point support	
Sizes	13 PN	10 PN	Removal of 12", 13", 15"	
LHD & RHD	Common usage	LHD & RHD differentiation	E.g. DDS-020R, DDS-020L	
Packaging	Window	No Window	-	
Packing	Individual box > 10pcs in	Individual box > 10pcs	Carton box increased strength	
Standard	inner carton box > 20pcs in outer carton box	carton box		
OGC Order	20pcs	10pcs	-	
Lot Size				

<Current Vs New Design>



<Schedule>

Please refer to monthly Aftermarket News for more details on status of PN running change.



2. Phased Out Applications

Background

The following additional DDS wiper blade PN in red will be phased out by this month.

The rest of PNs in the table have been phased out in previous months.

Some has replacement PNs that will be split into RHD and LHD PNs.

Phased Out Part No		Replacement Part No (if any)				
		RHD Part No		LHD Part No		
DDS-013	DI261622-0020			-		
DDS-014	DI261622-0030	DDS-014R	DI261622-0740	DDS-014L	DI261622-0840	
DDS-015	DI261622-0040			-		
DDS-016	DI261622-0050	DDS-016R	DI261622-0750	DDS-016L	DI261622-0850	
DDS-018	DI261622-0070	DDS-018R	DI261622-0770	DDS-018L	DI261622-0870	
DDS-022	DI261622-0110	DDS-022R	DI261622-0810	DDS-022L	DI261622-0910	
DDS-024	DI261622-0120	DDS-024R	DI261622-0820	DDS-024L	DI261622-0920	
DDS-026	DI261622-0130	DDS-026R	DI261622-0830	DDS-026L	DI261622-0930	

Next Action

Please stop ordering the phased out Part Nos, and order the replacement Part Nos if available.

3. Wrong Carmaker PN

COOL GEAR Radiator

<Background>

In Mar'21 of new vehicle applications for COOL GEAR Radiator,

It was wrongly indicated for the carmaker PN for Honda Vezel 2015.

<Revision>

The correct carmaker PN is <u>19010-50T-901</u>, not 10015529.

Please refer to the amendments in red below:

Car	Model	Year	Carmaker PN	DENSO PN	Oil	CG PN
Maker					Cooler	
HONDA	VEZEL	2015	10015529 19010-50T-901		Without	DI261470-3950#

*New Part No

For more information, please contact your DENSO Sales Company.