

# Aftermarket News (Sep'19)

## 1. New Product



Introducing new product from DENSO – DENSO Diesel Fuel Filter (DFF).

Comes with high filtration efficiency and high water separation efficiency\*

Actual launch timing may differ by country. Please approach your DENSO representative for more details.

*\*only applies for vehicle applications with water separator*

Please see below available major vehicle applications

Car Maker	Model	Year	Carmaker PN	DENSO Part No
FORD	RANGER/EVEREST	2011-	AB39-9176-AC	<a href="#">KS086300-4080</a>
ISUZU	D-MAX/MU-X	2012-	8-98159-693-0 / 8-98194-119-0	<a href="#">KS086300-2720</a>
MAZDA	BT-50	2011-	U2Y0-13-ZA5	<a href="#">KS086300-4080</a>
MITSUBISHI	TRITON/PAJERO SPORT	2005-, 2015-	1770A233 / 1770A321	<a href="#">KS086300-2720</a>
MITSUBISHI	TRITON/PAJERO SPORT	2005-, 2015-	1770A337 / 1770A338	<a href="#">KS086300-4110</a>
TOYOTA	HIACE/REGIUS ACE	2004-	23390-0L010 / 23390-0L040/ 23390-0L041	<a href="#">KS086300-2720</a>
TOYOTA	HILUX/FORTUNER/INNOVA	2004-	23390-0L010 / 23390-0L040/ 23390-0L041	<a href="#">KS086300-2720</a>
TOYOTA	HILUX/FORTUNER/INNOVA	2015-	23390-0L070	<a href="#">KS086300-4040</a>

## 2. New Vehicle Applications

### a. DENSO Condenser Fan Motor

Car Maker	Model	Year	Carmaker PN	DENSO PN	DENSO Aftermarket PN
HONDA	ACCORD/ CROSSTOUR	2010-2013	19030-R74-003 19030-RL9-H013-M1 19030-R77-T01 19030-R70-A01	168000-8650 AC168000-8651 AE168000-8650 AX168000-8650	<b>AC268000-2420<sup>#</sup></b>
HONDA	ACCORD/ CROSSTOUR	2014	19030-50C-H010-M1	AC268000-2190	<b>AC268000-2420<sup>#</sup></b>
HONDA	ACCORD/ SPIRIOR	2008 / 2011-2012	38616-R74-003 38616-R76-H013-M1 38616-R77-T01 38616-R70-A01	168000-8660 AC168000-8661 AE168000-8660 AX168000-8660	<b>AC268000-2410<sup>#</sup></b>
HONDA	ACCORD/ SPIRIOR	2013-2014	19030-5A2-A012-M1	AC268000-2021	<b>AC268000-2390<sup>#</sup></b>
HONDA	ACCORD/ SPIRIOR	2013-2014	38616-5G0-A012-M1	AC268000-2012	<b>AC268000-2410<sup>#</sup></b>
HONDA	ELYSION	2012-2014	19030-RKC-003 19030-R28-H012-M1	168000-7730 AC168000-7730	<b>AC268000-0240<sup>#</sup></b>
HONDA	ELYSION	2012-2014	38616-RKC-003 38616-R28-H012-M1	168000-7740 AC168000-7740	<b>AC268000-0230<sup>#</sup></b>
HONDA	JADE	2013	16363-28420 38616-5M1-H011-M	AC268000-2070	<b>AC268000-2400<sup>#</sup></b>
HONDA	JADE		38616-RBJ-0035	AC168000-7480	<b>AC268000-2400<sup>#</sup></b>
SUZUKI	CELERIO		17120-76M00-000	AC268000-6040	<b>AC268000-6150<sup>#</sup></b>
TOYOTA	CAMRY HV	2012	16363-36070 16363-0V260-B 16363-0V220 16363-0V150	168000-1130 AC168000-1131 AE168000-1130 AX168000-1130	<b>AC268000-0270<sup>#</sup></b>
TOYOTA	EFC II (VIOS)	2013-2014	16363-0Y040	AC268000-8030	<b>AC268000-8170<sup>#</sup></b>
TOYOTA	EFC II (VIOS)	2014 / 2016	16363-0Y050	AC268000-8060	<b>AC268000-8170<sup>#</sup></b>
TOYOTA	HIGHLANDER	2009 / 2012	16363-46170 16363-0P210-B 16363-0P190	168000-9220 AC168000-9220 AE168000-9220	<b>AC168000-2980<sup>#</sup></b>
TOYOTA	HIGHLANDER	2012	16363-20270 16363-0V250-A 16363-0P080	168000-7140 AC168000-7140 AE168000-7140	<b>AC268000-0280<sup>#</sup></b>
TOYOTA	HIGHLANDER	2015	16363-0V410	AC168000-1780	<b>AC268000-0280<sup>#</sup></b>
TOYOTA	HIGHLANDER	2015	16363-0V420-A	AC168000-2701	<b>AC168000-2970<sup>#</sup></b>
TOYOTA	RAV4	2013 / 2016	16363-0V380-A	AC168000-1570	<b>AC268000-0260<sup>#</sup></b>
TOYOTA	RAV4	2013 / 2016	16363-36160 16363-0V390	168000-1490 AC168000-1490	<b>AC268000-0250<sup>#</sup></b>

<sup>#</sup>New Part No

### b. COOL GEAR Air Filter

Car Maker	Model	Engine Type	Year	Carmaker PN	CG PN	Type
TOYOTA	AVANZA	3SZ-VE, 2NR-VE	2012	17801-BZ150	<b>260300-0800</b>	PU

### 3. Packaging Box Design Change

#### Spark Plug – 2W Packaging Box

##### <Background>


Due to Customer Protection Law Requirement in each country, we revised the packaging box of our maintenance products to include in local language\*

\*countries with DENSO office presence will include local language as required by law.

The 2W spark plug packaging box will now follow common design as 4W spark plug packaging box.  
 Below is new design.

##### <New Design>

###### (1pc example)



##### <Change Point>

- 1) Add "Caution" image
- 2) Multi language (C/O, Product Name)
- 3) QR Code links to DENSO web page

###### (10pc example)



##### <Change Point>

- 1) Multi language (C/O, Product Name)

**<Schedule>**

Packaging box will be revised by running change, as below information.

Box Change Timing	Part No	Description
Step-1/Aug~	JK067800-1640	U16FS-U
	JK067800-1650	U20FS-U
	JK067800-1660	U22FS-U
	JK067800-1700	X24ES-U
	JK067800-5080	X24EP-U9
	JK067800-6810	U24ES-N
	JK067800-6820	U24ESR-N
	JK067800-6871	U20EPR9
	JK067800-7310	U22FSR-U
	JK067800-7510	U16FS-U
	JK067800-7520	U20FS-U
	JK067800-7680	U22ES-N
	JK067800-7700	XU22EPR-U
	JK067800-8290	XU22PR9
Step-2/Sep~	JK067800-1690	X22ES-U
	JK067800-1780	X20FS-U
	JK067800-1830	X24EP-U
	JK067800-6690	U27ESR-N
	JK067800-7061	U22EPR9
	JK067800-7300	X24EPR-U9
	JK067800-7360	U20FSR-U
	JK067800-7420	U24EPR9
	JK067800-7480	U22FER9
	JK067800-7530	U22FS-U
	JK067800-7610	X24ESR-U
	JK067800-7650	U27FER9
	JK067800-7690	XU22EP-U
	JK067800-7720	XU24EPR-U R
	JK067800-7730	X22EPR-U9
	JK067800-7800	XU20HR9
	JK067800-7830	U27ES-N
JK067800-7840	U27EPR9	
Step-3/Oct~	JK067800-1820	X22EP-U
	JK067800-7500	U24FER9
	JK067800-7620	U16FSR-U
	JK067800-7640	U24FER9 R
	JK067800-7660	U20ESR-N
	JK067800-7670	U22ESR-N
	JK067800-7740	X27EPR-U9
JK067800-7750	U20EPR9S	

For more information, please contact your DENSO Sales Company.