

## Aftermarket News (Jun'22)

### 1. New Vehicle Applications

#### a. COOL GEAR Radiator

Car Maker	Model	Year	Carmaker PN	DENSO PN	Oil Cooler	CG PN
HYUNDAI	I30	2014-2017	253103X650		With	<a href="#">DI261470-4360</a> <sup>#</sup>
KIA	MORNING		25310-1Y300		Without	<a href="#">DI261470-4340</a> <sup>#</sup>
MAZDA	2	2015	P53W15200	TG422135-6570	Without	<a href="#">DI261470-4370</a> <sup>#</sup>
mitsubishi	LANCER	2008-2009	1350A298		With	<a href="#">DI261470-4400</a> <sup>#</sup>
TOYOTA	CAMRY	2012-2017	16400-0V170	TG422174-7680	With	<a href="#">DI261470-4350</a> <sup>#</sup>
TOYOTA	PRADO	2002-2010	16400-75440	422132-8063	With	<a href="#">DI261470-4380</a> <sup>#</sup>
TOYOTA	YARIS	2013-2016	16400-0M220	TG422135-1473	With	<a href="#">DI261470-3980</a> <sup>#</sup>

<sup>#</sup>New Part No

#### b. COOL GEAR Cabin Air Filter

Car Maker	Model	Year	Carmaker PN	DENSO PN	CG PN
HONDA	CIVIC	2016-	80292-TJA-H01		<a href="#">DI261401-5100</a>
HONDA	CR-V	2017-	80292-TJA-H01		<a href="#">DI261401-5100</a>
HONDA	HR-V	2015-	80292-TJA-H01		<a href="#">DI261401-5100</a>

<sup>#</sup>New Part No

Please continue to next page

## 2. Imitation Alert – COOL GEAR Radiator Cap

### COOL GEAR Radiator Cap

<Background>

DENSO Regional is alerted to fake COOL GEAR Radiator Cap in the market.

The fake packaging is similar to the original, however, the radiator cap inside is green in color.



<Next Action>

Please take note of this and do not buy the fake radiator cap.

### 3. Packaging Change – DENSO Spark Plug

#### (a) Iridium Power Spark Plug

<Background>

To cater for requirements for Customer Protection Law and Trade Law regulations, DENSO Iridium Power Spark Plug box design will be changed.

<Results>

Packaging box will be revised, based on running changes, from July 2022 production.

Below table shows the details of revised packaging box (flat layout view):

Type	Before Jul'22 production	After Jul'22 production
1pc box		
4pc box		

**(b) Reminder: Nickel Spark Plug (made in China)**

<Background>

To cater for requirements for Customer Protection Law and Trade Law regulations, DENSO Spark Plug box design will be changed.

<Results>

Packaging box will be revised, based on running changes.  
 Spark plug Made in China has already proceeded the change as of October'21 production.

Below table shows the details of revised packaging box (flat layout view):

Type	Before Oct'21 production	From Oct'21 production
1pc box		
10pc box		

### 4. (Reminder) Minor Update in Bottle Label – DENSO Engine Oil

#### DENSO Engine Oil

<Background>

As an effort to simplify the content in DENSO Engine Oil bottle label, add in product name and MOE logo for Thailand requirements, the back label (non-Indonesian version) will be progressively updated.

<Results>

Bottle labels (non-Indonesian version of back label only) will be progressively updated, starting with Platinum 5W-40, on running change basis, from April 2022 shipment onwards.

Below table shows the details of revised bottle label, using example for Platinum 5W-40, 1L type.

Current (sample Part No, 1L)	New (sample Part No, 1L)
<p>The current label for DENSO Engine Oil Platinum 5W-40 (1L) includes the following text:</p> <p><b>DENSO Engine Oil Platinum</b>      Contains: Alkylaryl amine, ZnDTP, Magnesium sulfonate</p> <p>1. Always check and follow the instructions in the car manual to avoid the use of wrong products.      2. A complete oil change, including change of oil filter, is recommended when changing to DENSO engine oil to fully utilize the product benefits.      3. Do not use for faulty engine. Engine oil may clean up faulty seals and may cause engine oil to leak or start oil consumption.</p> <p><b>Precautionary Statement:</b> - General: Irritantly remove any clothing soaked by product. - Inhalation: Supply fresh air, consult doctor in case of symptoms.      - Eye contact: Promptly wash eyes with plenty of water while lifting the eye lids.      - Skin Contact: Wash with soap and water. - Ingestion: Rinse mouth thoroughly.      - Most important symptoms and effects, both acute and delayed: May cause skin and eye irritation. - Indication of any immediate medical attention and special treatment needed: Get medical attention if symptoms occur.</p> <p><b>Handling and storage:</b> - Precautions for safe handling: Prevent formation of aerosol. Do not eat, drink or smoke when working with the product. Take usual precaution when handling mineral oil product or chemical products. Observe good industrial hygiene practice. Provide adequate ventilation. Keep container tightly closed. - Conditions for safe storage, including any incompatibilities: Local regulation concerning handling and storage of water polluting products have to be followed. Do not heat up temperatures close to the flash point.</p> <p><b>Hazard Statement:</b> - Fatal if swallowed and enters airways. - Causes serious eyes damage.</p> <p>Applicable for Gasoline engine requiring API SN II diesel engine requiring API CF.      Meets: ACEA A3/B4, MB 229.3, VW 502 00 / 505 00.</p> <p>Includes distributor information for Singapore, Malaysia, Indonesia, and the Philippines.</p>	<p>The new label for DENSO Engine Oil Platinum 5W-40 (1L) includes the following text:</p> <p><b>DENSO Engine Oil Platinum 5W-40</b>      Contains: ZnDTP, Carbonate</p> <p>1. Always check and follow the instructions in the car manual to avoid the use of wrong products.      2. A complete oil change, including change of oil filter, is recommended when changing to DENSO engine oil to fully utilize the product benefits.      3. Do not use for faulty engine. Engine oil may clean up faulty seals and may cause engine oil to leak or start oil consumption.</p> <p><b>Precautionary and Hazard:</b> - Store in a well-ventilated place. - Keep container tightly closed. - Dispose of container/residue in accordance with applicable local/regional/international regulation. - May produce an allergic reaction. - Safety data sheet available on request. - Do not eat, drink or smoke when working or handling the product. - Take usual precaution when handling mineral oil products or chemical products.</p> <p>Applicable for Gasoline engine requiring API SN II diesel engine requiring API CF.      Meets: ACEA A3/B4, MB 229.3, VW 502 00 / 505 00.</p> <p>Includes distributor information for Singapore, Malaysia, Indonesia, and the Philippines, along with the MOE logo and Thai text.</p>

### 5. (Reminder) Packaging Change – COOL GEAR Oil Filter

#### COOL GEAR Oil Filter

<Background>

In line with global packaging guidelines, COOL GEAR Oil Filter box design will be changed.

<Results>

Packaging box will be revised, based on running changes, from June 2022 shipment onwards.

Below table shows the details of revised packaging box (flat layout view):

\*All new COOL GEAR Oil Filter launches are already with the revised packaging design.

Type	Spin-On
Current Packaging	
New Packaging	

Type	Element
Current Packaging	
New Packaging	

## 6. (Reminder) Label Change –COOL GEAR Expansion Valve

### COOL GEAR Expansion Valve

<Background>

In line with global packaging guidelines, label of COOL GEAR Expansion Valve will be revised.

<Results>

Label will be revised on a running change basis from end April shipment onwards, starting with following Part Nos:

- 047500-9072
- 447500-9250
- 447500-9220
- 447500-9052
- 447500-9071
- 447500-8210

Below table shows the details of revised Part No. Label:

Current Label	New Label
	

For more information, please contact your DENSO Sales Company.