

## Aftermarket News (Dec'23)

### 1. Change in Part No. – COOL GEAR Condenser

#### COOL GEAR Condenser

<Background>

Due to Separator, End Cap and Cap Modulator improvement and change, 5 Part No. of COOL GEAR Condenser DP type will be affected.

<Results>

The affected COOL GEAR Condenser will change the last digit of the Part No. to "1" in upcoming shipments with immediate effect.

Below are the affected Part No.

Current Part No	New Part No
DI261433-0250	DI261433-0251
DI261433-0260	DI261433-0261
DI261433-0270	DI261433-0271
DI261433-0290	DI261433-0291
DI447780-3560	DI447780-3561

<Next Action>

Please order using the updated Part No. with immediate effect.

For more information, please contact your DENSO Sales Company.