

# Aftermarket News (Jul'22)

## 1. New Vehicle Applications

### a. COOL GEAR Air Filter

Car Maker	Model	Engine Type	Year	Carmaker PN	CG PN	Type
FORD	BANTAM	ROCAM A9JD	2006-2009	6S69 9601 AA	<b>DI260300-1470#</b>	PU
VOLKSWAGEN	CITI GOLF	AGY62KW	2002-2009	6KS-129-620A	<b>DI260300-1520#</b>	PU

#New Part No

## 2. Change in Part No – DENSO Engine Oil Silver 15W-40

### DENSO Engine Oil

<Background>

DENSO Engine Oil Silver 15W-40 will change to new formulation.

The reason for this change is to combat fuel dilution for Biodiesel application which is a common operation behaviour among biodiesel application. High fuel dilution rate can greatly affect the engine oil performance in the long run and hence, this improvement is to better suit the operating conditions of Biofuels application in Southeast Asia.

API Level	SAE	Bottle size (L)	DENSO Part No.	New DENSO Part No.	Product Name
CF-4	15W-40	1	DI260390-0230	<b>DI260390-0231</b>	DENSO Engine Oil Silver 15W40 (1L)
CF-4	15W-40	4	DI260390-0240	<b>DI260390-0241</b>	DENSO Engine Oil Silver 15W40 (4L)
CF-4	15W-40	20	DI260390-0250	<b>DI260390-0251</b>	DENSO Engine Oil Silver 15W40 (20L)

Appearance change in bottle using 1 litre as example:

Label	Current	New
Front Label		<p>Temporary as a stick-on to show the new Part No.              Please ignore the Part No shown as it is not correct.</p>

**Back Label**

**Added.**

**Other changes due to content simplification, some country requirements but not related to formulation change.**

**<Next Action>**  
Please order the new Part Nos from July'22 PO.

### 3. Ink Stamp Removal and Packaging Change – COOL GEAR Radiator

#### COOL GEAR Radiator

<Background>

Ink stamp on COOL GEAR Radiators have been removed from 1<sup>st</sup> July PO onwards.


Example of ink stamp that will be removed:






Some POs placed before 1st July'22 but have not start production yet will have the ink stamp removed too, below are the affected Part Nos:

422175-7410	261470-2430	422176-0240	422176-1860
261470-0010	422175-5570	422176-0260	422176-1870
261470-0090	422175-5600	422176-1050	422176-2580
261470-0110	422175-6420	422176-1050	422176-4490
261470-0320	422175-7390	422176-1100	422176-4510
261470-0630	422175-7970	422176-1110	D1261470-3960
261470-1090	422175-7980	422176-1520	D1261470-4350
261470-1900	422175-8000	422176-1570	
261470-2150	422175-8030	422176-1600	

For the current packaging, there will be a marking made on the packaging box to inform the radiators do not have ink stamp (marking of either a tick or a green circle sticker):



From 1<sup>st</sup> July PO onwards, the COOL GEAR Radiators will be packed in new packaging.  
 Details of new packaging and label as below:

Type	Current	New
Top Surface of box (all other surface print remain unchanged)		
Label	<p style="color: red;">&lt;information not available&gt;</p>	

<Next Action>

Please take note of the removal of ink stamp and new packaging.

### 4. Reminder: Packaging Change – DENSO Spark Plug

#### (a) Iridium Power Spark Plug

<Background>

To cater for requirements for Customer Protection Law and Trade Law regulations, DENSO Iridium Power Spark Plug box design will be changed.

<Results>

Packaging box will be revised, based on running changes, from July 2022 production.

Below table shows the details of revised packaging box (flat layout view):

Type	Before Jul'22 production	After Jul'22 production
1pc box		
4pc box		

**(b) Nickel Spark Plug (made in China)**

<Background>

To cater for requirements for Customer Protection Law and Trade Law regulations, DENSO Spark Plug box design will be changed.

<Results>

Packaging box will be revised, based on running changes.

Spark plug Made in China has already proceeded the change as of October'21 production.

Below table shows the details of revised packaging box (flat layout view):

Type	Before Oct'21 production	From Oct'21 production
1pc box		
10pc box		

For more information, please contact your DENSO Sales Company.